


平成23年4月～平成24年3月 BOD平均値 (mg/リットル)



【参考】
環境基準(河川)
A類型: 2mg/リットル

採水基準日	H23 4/1	4/16	5/6	5/17	6/1	6/16	7/1	7/16	8/2	8/16	9/1	9/16	10/ 1	10/18	11/1	11/16	12/1	12/16	H24 1/6	1/17	2/1	2/16	3/1	3/16	平均値
1 徳益・垂見 下田橋南側	3.3	2.6	1.7	6.4	4.9	7.7	8.9	5.3	4.2	3.2	3.9	2.6	8.1	3.0	5.7	3.7	4.9	3.1	3.2	0.6	3.5	3.9	5.5	4.2	4.3
2 南徳益 流川橋西側	6.6	18.5	0.8	2.5	5.4	7.4	7.1	2.1	2.4	1.8	4.2	13.6	13.8	7.9	14.2	11.8	5.4	9.3	4.1	3.8	5.3	1.9	1.9	23.8	7.3
3 豊原小学校西側	5.4	10.7	3.3	3.5	8.5	16.3	9.0	8.9	4.9	3.2	6.9	0.0	9.5	3.3	9.8	5.8	6.2	0.7	0.0	1.5	3.2	1.9	7.4	5.7	5.7
4 鷹尾交差点東側	24.4	26.5	20.8	11.5	18.3	44.9	4.8	5.9	8.3	4.5	6.4	12.5	8.8	6.1	26.5	11.7	13.5	3.0	3.8	2.5	9.4	4.5	1.8	16.7	12.4
5 皿垣小学校西側	3.9	5.8	2.4	4.9	8.6	27.0	11.7	1.1	7.0	19.2	4.0	11.2	25.8	3.1	11.7	18.1	8.8	3.5	4.0	3.9	5.6	5.7	10.7	25.6	9.7
6 二十五丁水門	1.5	6.9	2.4	2.2	2.7	12.8	44.6	5.8	7.1	3.1	5.3	3.7	3.2	2.5	11.1	7.8	16.1	7.3	5.8	3.4	5.7	3.9	5.1	2.6	7.2
7 中島二重 榑平河建材北側	1.3	5.5	5.4	12.8	3.1	1.4	1.0	7.5	3.4	0.9	3.9	2.7	3.3	1.4	2.9	3.4	11.8	4.5	4.2	0.6	6.3	3.0	4.5	6.7	4.2
8 中島東上町公民館西側	5.8	9.6	4.1	15.4	11.1	17.4	19.9	4.5	3.9	3.8	3.4	13.6	14.1	7.2	13.1	6.1	8.9	1.7	3.4	12.7	2.1	3.0	11.3	10.3	8.6
9 六合配水場東側	2.3	3.8	4.5	1.6	0.6	2.3	0.7	0.6	1.9	0.9	0.7	1.9	3.1	7.5	12.5	120.0	2.6	5.9	8.1	6.4	6.6	0.6	3.0	0.6	8.3
10 立花いこいの森駐車場南側	0.6	4.3	0.6	0.6	0.6	0.6	0.6	0.6	1.6	0.6	0.6	0.9	0.6	0.6	1.6	1.8	1.0	0.6	0.6	0.6	2.3	0.6	0.9	0.6	1.0
11 百町 ニツ川樋管	0.6	1.0	0.6	0.6	0.6	0.6	0.6	0.6	0.6	0.6	1.0	0.7	0.6	0.6	0.6	1.3	1.4	0.8	0.6	0.6	1.5	0.6	0.9	0.6	0.8
12 吉開納骨堂西側	0.6	1.7	1.4	0.9	1.5	9.7	1.0	0.7	3.3	0.6	0.6	1.8	1.6	1.3	3.1	4.0	2.5	1.0	0.6	0.6	0.6	0.7	4.7	6.9	2.1
13 起田天満神社北側	2.2	3.0	1.1	2.1	6.7	11.8	2.3	3.2	5.8	1.1	2.1	3.0	2.1	1.7	3.9	4.8	3.2	4.5	1.4	1.5	3.8	4.3	4.5	6.3	3.6
14 磯鳥ポンプ場北側	1.5	2.4	3.4	0.6	0.6	4.3	2.3	1.3	1.8	0.8	0.6	2.6	1.4	2.7	3.3	3.2	0.7	1.9	0.6	2.9	3.1	0.6	2.4	3.1	2.0
15 散田ニツ川有明海沿岸道路東側	0.6	1.3	0.6	0.7	0.6	0.6	0.9	0.8	1.3	0.6	0.6	1.8	1.0	1.1	0.6	1.8	2.1	0.6	0.6	0.6	1.1	0.6	0.6	0.6	0.9
16 柳川駅南側	0.6	2.3	0.7	2.5	1.0	1.7	6.4	6.3	5.9	1.6	1.1	4.0	1.9	2.5	14.5	5.5	7.4	4.8	7.3	8.3	15.1	1.8	5.8	6.2	4.8
17 枝光 小坪樋管	1.4	5.1	2.5	4.1	0.8	11.4	2.1	2.5	2.4	0.9	1.3	0.7	1.8	2.2	5.3	7.9	7.4	5.9	4.8	5.3	6.6	4.6	7.3	5.0	4.1
18 三柱神社西側 宮地嶽ポンプ場	1.8	4.3	2.1	2.4	11.1	0.6	1.0	1.4	1.6	0.6	2.7	0.7	2.3	1.9	0.6	4.0	1.9	6.4	0.6	1.5	5.6	0.6	0.7	0.8	2.4
19 柳川市葬儀取扱所北側	0.8	0.7	4.2	0.6	1.8	0.6	0.6	0.9	2.7	0.7	1.0	1.0	1.4	0.8	1.1	2.1	1.1	2.5	0.7	1.9	0.6	0.6	0.6	0.6	1.2
20 坂本町 弥兵衛門橋	0.7	2.5	1.0	1.8	0.9	2.5	0.6	1.0	2.7	0.6	1.6	0.7	1.5	2.5	5.7	2.4	0.7	1.5	0.6	0.8	1.3	0.6	0.6	0.6	1.5
21 松濤園南側 八幡樋管	0.6	4.7	2.9	1.4	0.6	3.7	0.9	2.2	2.1	1.5	2.5	0.0	1.7	4.0	1.1	3.0	2.7	2.4	0.6	0.8	2.6	0.6	4.5	0.7	2.0
22 東宮永小学校東側	0.6	1.4	1.6	3.7	3.4	8.0	1.6	0.9	1.3	11.5	1.5	7.5	66.8	1.6	3.4	3.4	0.8	1.1	0.6	0.6	1.5	0.6	1.9	1.0	5.3
23 中六十丁公民館西側	2.7	7.5	7.8	2.1	7.9	9.7	21.3	7.7	5.4	2.9	3.8	3.1	9.4	3.4	8.8	5.0	3.2	4.9	0.6	0.9	2.6	0.9	2.6	5.5	5.4
24 高島 忠六別水門	4.2	5.3	12.7	5.4	7.3	12.6	12.0	1.3	5.4	2.1	1.3	1.1	4.9	4.1	6.7	6.9	5.8	3.0	0.6	1.7	2.5	1.5	7.5	4.0	5.0
25 金納橋	3.0	4.5	13.8	3.8	7.3	16.1	16.2	4.3	10.4	3.8	4.3	2.7	7.1	9.9	8.6	11.7	11.8	7.5	3.4	3.5	5.8	7.9	4.2	2.1	7.2
26 東蒲池 榎木いび	5.1	4.2	20.8	2.1	6.3	12.0	17.6	5.3	3.3	3.4	1.7	1.9	5.0	3.1	4.7	6.5	4.1	2.9	3.5	3.3	7.3	1.6	7.3	5.6	5.8
27 西浜武 NEC東側	4.0	7.0	4.7	4.0	7.4	17.4	8.5	4.9	2.6	2.9	1.0	1.4	4.8	2.6	5.1	8.3	5.9	2.9	2.2	1.5	6.5	0.9	9.6	3.3	5.0
28 昭代第二小学校西側	6.9	7.5	5.4	2.3	4.8	19.4	14.1	6.6	5.4	2.7	1.8	3.5	6.2	3.4	6.6	7.9	6.9	3.9	3.0	1.6	7.2	4.1	9.8	9.1	6.3
29 吉原南バス停東側	6.4	7.4	7.8	4.8	8.0	44.0	18.1	5.9	3.2	4.0	1.9	2.9	6.4	3.5	11.9	13.0	6.6	3.5	4.1	1.4	45.1	3.1	10.2	17.8	10.0
30 柳川みのり幼稚園東側	8.5	9.6	6.1	5.4	8.1	23.8	23.5	10.5	3.2	5.4	7.3	3.8	7.8	4.7	8.6	15.2	7.7	5.8	3.7	3.4	8.0	5.0	7.9	7.4	8.4
31 間 九郎丸橋	30.2	33.6	13.0	7.5	15.7	26.7	24.7	18.1	3.9	8.2	7.2	8.6	11.5	7.0	8.2	17.4	12.1	9.0	5.9	6.3	13.0	9.3	15.4	15.4	13.7
32 昭代6号線 池町制水門	5.8	13.0	6.5	3.2	7.7	27.2	19.2	7.7	6.1	4.0	2.1	4.9	9.8	5.6	10.4	21.0	9.8	9.3	4.8	6.5	12.9	6.5	10.7	10.3	9.4
平均	4.5	7.0	5.2	3.9	5.4	12.6	9.5	4.3	3.9	3.2	2.8	3.8	7.7	3.5	7.2	10.8	5.8	3.9	2.8	2.9	6.4	2.7	5.4	6.6	5.5