


# 平成30年4月～平成31年3月 平均BOD値(mg/リットル)



**【参考】**  
 環境基準(河川)  
 A類型: 2mg/L

平成30年度 BOD(mg/l)測定結果

採水日	4/2	4/16	5/1	5/16	6/1	6/18	7/2	7/17	8/1	8/16	9/3	9/18	10/1	10/16	11/1	11/16	12/3	12/17	1/4	1/16	2/1	2/18	3/1	3/18	平均値
1 徳益・垂見 下田橋南側	1.4	0.8	0.6	0.9	1.8	5.8	11.9	2.7	2.8	1.9	3.2	0.6	1.7	1.2	0.6	3.3	1.1	3.1	1.2	0.6	0.6	0.6	2.2	1.5	2.2
2 南徳益流川橋西側	16.6	14.9	7.7	8.6	11.6	19.4	10.2	11.7	12.3	1.7	2.5	1.2	7.7	14.5	10.4	7.9	17.1	15.8	5.1	14.3	3.5	14.8	3.5	8.4	10.1
3 豊原小学校西側	3.1	1.1	2.5	1.9	0.6	7.4	9.6	4.5	6.6	3.7	3.0	4.4	9.7	5.2	1.2	6.5	11.8	4.8	6.5	2.6	2.0	1.7	11.1	5.4	4.9
4 鷹尾交差点東側	4.8	1.8	1.7	4.0	3.2	11.0	7.8	7.7	8.5	5.8	4.6	3.4	7.4	11.6	9.6	12.0	4.3	7.8	0.9	3.4	1.7	17.2	5.4	9.8	6.5
5 皿垣小学校西側	3.1	1.2	0.7	1.1	8.6	9.0	22.7	5.7	9.6	4.5	5.1	1.1	3.3	6.1	1.3	5.7	4.7	4.4	0.6	1.5	7.3	0.6	3.0	5.8	4.9
6 二十五丁水門	4.8	1.2	1.3	1.2	1.1	29.3	36.6	7.0	4.3	6.8	3.1	5.9	9.4	6.3	2.5	13.2	10.9	4.5	3.4	2.6	0.6	0.8	7.4	11.2	7.3
7 中島二重橋平河建材北側	6.3	2.2	18.9	2.5	3.7	9.6	1.4	4.1	1.9	2.0	1.5	1.3	1.4	7.8	2.7	8.0	5.7	6.0	6.0	4.6	1.3	3.9	4.5	8.3	4.8
8 中島東上町公民館西側	18.2	3.3	1.3	37.8	8.5	7.6	6.5	4.8	6.7	5.1	4.8	2.6	2.2	15.1	4.3	13.2	4.3	15.3	9.7	2.5	1.3	5.3	1.9	14.2	8.2
9 六合配水場東側	3.5	2.7	0.7	0.6	0.6	5.2	8.1	3.7	1.2	3.1	1.9	0.6	1.3	7.2	2.5	5.4	3.1	3.4	3.1	1.1	1.3	0.6	3.3	4.7	2.9
10 立花いこいの森駐車場南側	2.4	1.1	0.6	0.6	0.6	0.6	0.7	2.0	0.6	0.6	1.7	0.6	0.9	7.6	1.3	5.0	2.7	3.3	0.6	0.8	1.4	0.6	2.8	1.9	1.7
11 百町 ニツ川樋管	2.4	0.9	0.6	0.6	0.6	0.8	0.7	1.9	12.4	0.6	3.2	0.6	0.9	7.8	1.3	3.4	2.2	3.0	0.6	1.5	2.2	0.6	4.3	2.5	2.3
12 吉開納骨堂西側	2.6	1.7	0.8	0.6	1.8	2.0	5.7	9.4	9.9	0.6	2.6	0.7	2.6	10.0	1.7	3.5	4.1	7.1	1.8	2.5	2.2	1.4	4.8	4.7	3.5
13 起田天満神社北側	3.5	2.0	1.8	1.2	3.7	7.7	7.2	7.2	9.1	3.8	3.8	1.1	5.8	9.9	4.0	6.3	5.5	4.1	5.8	4.4	2.0	0.6	3.3	3.7	4.5
14 磯島ポンプ場北側	3.5	1.1	0.8	0.6	0.6	4.6	13.1	3.3	7.6	1.2	2.7	0.6	2.2	7.1	1.3	5.3	2.1	3.1	0.6	2.4	3.0	0.6	4.4	2.2	3.1
15 散田 ニツ川有明海沿岸道路東側	1.7	0.9	0.6	0.6	0.6	0.8	0.6	3.7	4.3	0.6	2.0	0.8	1.2	7.2	1.2	3.9	3.8	1.3	0.6	0.8	1.9	0.6	3.7	1.5	1.9
16 柳川駅南側	8.4	1.3	3.2	2.7	5.1	4.0	8.4	5.8	3.2	3.5	5.3	5.0	6.5	7.3	2.0	18.9	4.6	2.2	5.4	2.8	3.2	6.4	4.3	8.7	5.3
17 枝光小坪樋管	2.1	1.5	0.8	0.7	1.9	3.5	8.7	5.1	2.1	2.2	4.0	2.1	2.8	7.7	4.3	8.1	6.0	4.6	2.7	2.5	1.4	0.6	3.5	4.7	3.5
18 三柱神社西側 宮地嶽ポンプ場	0.9	0.9	0.8	0.8	1.1	0.8	1.3	6.5	3.9	1.5	3.8	1.3	1.8	6.0	1.5	5.2	5.9	1.7	0.6	1.1	1.3	0.6	4.0	4.1	2.4
19 柳川市葬祭取扱所北側	1.2	1.1	1.9	0.8	2.2	1.5	1.3	3.3	1.8	1.4	3.3	1.2	2.1	6.5	1.5	4.5	5.3	1.4	1.8	1.2	2.0	0.6	2.6	2.7	2.2
20 坂本町 弥兵衛門橋	0.6	0.7	1.5	0.6	0.9	1.9	2.7	4.5	2.1	1.9	3.1	0.8	3.4	6.1	2.4	4.5	3.3	1.7	0.6	0.8	1.4	0.6	2.1	5.3	2.2
21 松濤園南側 八幡樋管	0.7	0.7	1.1	0.6	2.0	2.2	3.4	2.2	2.5	3.3	3.3	1.4	2.7	7.0	2.2	5.7	6.0	2.8	1.7	0.9	1.9	1.3	3.3	3.3	2.6
22 東宮永小学校東側	0.6	1.3	1.8	0.6	2.0	2.0	16.6	3.2	1.3	1.7	2.4	0.6	4.6	7.3	2.5	5.8	5.5	2.7	0.6	0.9	4.5	0.6	2.5	4.5	3.2
23 中六十丁公民館西側	1.9	1.3	2.2	1.1	4.0	13.7	20.5	8.0	6.8	6.1	3.9	1.2	7.9	8.1	4.6	9.2	6.1	4.0	2.7	0.9	9.9	1.2	4.1	8.5	5.7
24 高島 忠六別水門	2.0	1.2	1.5	1.2	3.3	7.9	17.9	6.1	1.1	3.1	3.3	0.9	3.7	7.8	3.9	7.9	3.5	1.8	2.1	2.1	2.6	0.6	3.1	6.6	4.0
25 金納橋	2.0	1.3	2.7	0.8	4.1	7.2	18.9	5.5	5.0	4.6	5.0	1.2	3.4	6.0	6.8	8.3	3.9	2.7	2.7	1.4	3.0	0.8	2.0	7.3	4.4
26 東蒲池 榎木いび	1.9	1.7	3.1	0.8	3.1	7.0	21.0	5.9	4.1	3.2	4.0	1.2	4.5	8.6	8.1	8.9	3.8	1.7	3.7	2.1	2.8	1.2	5.8	10.4	4.9
27 西浜武ファインテック東側	1.7	1.7	2.1	0.7	2.5	5.0	14.9	4.8	3.5	4.3	5.1	1.1	5.4	6.5	7.8	9.6	5.0	3.4	3.4	2.4	3.1	0.7	6.3	7.3	4.5
28 昭代第二小学校西側	0.9	1.7	3.8	0.9	4.4	6.0	16.6	6.5	5.1	3.8	6.6	2.1	4.6	6.6	8.1	9.2	2.6	3.8	3.0	2.7	5.1	0.8	5.8	6.6	4.9
29 吉原南バス停東側	3.2	2.6	2.6	1.1	4.5	17.5	32.8	8.0	11.9	8.6	5.4	1.7	8.7	6.5	7.9	10.4	9.6	4.4	5.5	2.8	2.8	1.3	3.5	6.1	7.1
30 柳川みのり幼稚園東側	5.7	3.0	3.2	1.1	3.5	10.9	21.3	7.2	8.1	4.4	5.9	3.9	11.0	8.1	7.4	10.2	7.0	4.0	5.3	2.6	3.3	0.8	3.2	9.0	6.3
31 間九郎丸橋	5.7	4.8	3.5	0.9	4.7	12.2	14.3	8.1	7.4	10.6	8.5	5.0	13.9	11.1	11.7	15.1	9.1	6.5	12.0	4.8	5.5	4.4	4.7	10.9	8.1
32 昭代6号線 池町制水門	4.1	2.8	3.1	1.1	4.4	2.1	13.5	5.5	4.7	6.1	4.1	1.9	6.0	10.9	10.5	11.2	9.2	4.7	7.4	3.7	5.3	2.7	5.0	10.7	5.9
平均	3.8	2.1	2.5	2.5	3.2	7.1	11.8	5.5	5.4	3.5	3.8	1.8	4.7	7.9	4.3	8.0	5.6	4.4	3.4	2.5	2.9	2.3	4.1	6.3	4.6