


平成31年4月～令和2年3月 平均BOD値 (mg/リットル)



【参考】
 環境基準(河川)
 A類型: 2mg/L

令和元年度 BOD(mg/l)測定結果

採水日	4/1	4/16	5/8	5/16	6/3	6/17	7/1	7/16	8/1	8/16	9/2	9/17	10/2	10/16	11/1	11/18	12/2	12/16	1/6	1/16	2/3	2/17	3/2	3/16	平均値
1 徳益・垂見 下田橋南側	2.1	3.8	1.1	0.6	0.6	0.6	1.5	1.3	2.4	0.8	1.9	0.8	0.8	0.6	2.1	0.6	1.2	1.4	5.1	1.5	0.8	4.7	0.6	0.6	1.6
2 南徳益流川橋西側	22.2	13.3	19.1	13.1	5.9	20.5	2.4	5.3	26.0	4.4	4.0	16.8	27.2	56.7	18.9	29.5	20.8	23.8	18.9	20.3	20.5	11.8	2.8	15.3	17.5
3 豊原小学校西側	2.0	2.7	2.4	0.6	0.6	1.3	2.1	3.2	1.8	2.6	3.4	2.2	3.1	2.0	1.9	2.5	3.2	7.1	6.1	2.0	1.3	5.8	3.7	0.9	2.7
4 鷹尾交差点東側	5.9	5.4	9.0	14.2	5.2	7.4	2.8	3.0	3.4	4.0	7.1	6.6	3.7	0.7	8.1	6.0	7.1	8.1	13.7	6.7	1.3	5.7	2.4	0.6	5.8
5 皿垣小学校西側	5.7	4.0	3.3	0.6	0.6	2.8	1.8	3.2	4.1	1.4	6.3	2.2	3.0	0.8	1.4	3.7	2.1	7.7	6.3	2.1	1.2	5.2	1.5	0.6	3.0
6 二十五丁水門	7.1	3.5	3.7	0.6	0.8	13.0	3.0	3.7	2.1	1.2	4.1	3.1	4.0	0.7	3.5	3.1	2.2	6.6	4.7	1.2	1.1	4.6	1.3	0.9	3.3
7 中島二重橋平河建材北側	14.2	6.3	40.1	6.3	0.8	1.2	1.3	1.3	1.4	4.1	3.4	1.3	3.2	1.5	8.0	2.8	3.5	8.3	13.2	2.0	10.3	10.5	0.8	21.3	7.0
8 中島東上町公民館西側	5.5	5.2	8.1	2.1	4.3	5.0	1.7	5.0	2.7	1.8	4.4	4.6	4.7	2.0	9.4	4.8	3.7	9.4	10.5	0.7	2.1	5.5	1.7	1.3	4.4
9 六合配水場東側	5.4	5.8	5.5	0.6	0.6	2.1	1.5	3.1	1.5	1.4	5.0	0.6	2.8	0.6	2.0	3.3	1.5	7.9	5.1	3.4	1.7	2.5	0.9	0.7	2.7
10 立花いこいの森駐車場南側	6.8	3.1	3.4	0.6	0.6	1.5	1.2	2.7	0.6	2.5	2.5	0.6	2.1	0.6	1.2	1.9	1.3	12.3	6.8	3.0	1.7	2.5	0.6	0.6	2.5
11 百町 ニツ川樋管	6.6	4.8	4.0	3.5	0.6	0.9	1.5	3.7	0.6	2.0	2.2	0.6	1.8	1.4	0.6	3.0	2.6	8.5	7.3	0.8	0.9	1.7	0.7	0.6	2.5
12 吉開納骨堂西側	7.0	4.4	5.5	22.4	5.8	8.5	5.0	5.9	2.7	3.4	8.5	0.8	2.8	1.9	2.0	3.9	3.7	9.1	15.9	0.9	1.4	5.8	1.1	3.8	5.5
13 起田天満神社北側	6.4	5.5	7.1	12.2	10.6	14.8	2.4	6.1	5.0	4.0	10.6	7.0	4.0	8.5	6.4	4.0	5.1	16.5	24.1	1.4	1.8	3.1	2.2	2.6	7.1
14 磯島ポンプ場北側	8.9	6.5	6.4	17.2	5.7	2.6	1.9	2.4	0.8	2.4	3.1	0.6	3.4	0.6	2.5	3.2	3.5	8.6	9.0	0.9	1.3	4.1	1.3	1.2	4.1
15 散田 ニツ川有明海沿岸道路東側	6.1	5.2	4.3	0.6	4.0	2.6	2.7	3.1	0.7	4.0	4.7	0.7	1.8	0.6	0.6	1.8	1.3	10.5	8.0	0.6	0.9	0.7	0.6	0.6	2.8
16 柳川駅南側	8.1	5.9	3.9	4.1	4.6	7.4	3.3	5.0	0.8	6.3	6.1	1.7	5.3	0.6	2.6	1.9	2.7	9.4	9.4	0.6	3.0	3.1	1.9	0.6	4.1
17 枝光小坪樋管	7.6	5.4	4.5	5.1	6.1	7.3	3.1	4.8	0.9	3.7	5.2	2.5	3.3	0.8	4.6	3.4	4.8	7.3	9.3	1.7	3.0	1.4	1.5	1.4	4.1
18 三柱神社西側 宮地嶽ポンプ場	10.0	3.1	7.6	0.6	7.4	1.4	1.4	3.3	1.2	4.3	5.7	0.9	3.1	1.5	0.9	3.7	2.8	4.3	8.0	0.8	0.8	1.3	0.6	3.0	3.2
19 柳川市葬祭取扱所北側	7.3	2.1	7.3	0.6	4.7	2.8	1.2	3.5	1.3	3.2	4.4	1.1	4.3	0.9	1.1	2.0	2.6	6.0	8.0	0.6	1.2	5.4	1.3	0.6	3.1
20 坂本町 弥兵衛門橋	6.7	3.0	4.4	3.8	5.3	1.2	1.1	4.4	0.8	2.6	5.2	0.6	4.7	0.6	0.6	1.4	2.7	3.5	7.6	0.6	0.8	2.1	0.7	0.6	2.7
21 松濤園南側 八幡樋管	7.9	4.1	2.2	0.6	6.6	0.9	1.3	5.1	0.8	4.1	5.9	0.7	6.6	0.6	1.4	2.1	4.0	6.1	11.6	0.7	1.1	3.3	0.6	0.6	3.3
22 東宮永小学校東側	7.2	3.3	3.1	0.6	6.8	3.1	1.3	5.0	0.8	4.0	6.7	0.6	5.5	0.6	0.6	1.5	3.2	4.7	6.4	0.6	1.2	2.4	0.6	0.6	2.9
23 中六十丁公民館西側	6.6	2.1	2.8	1.7	7.4	6.6	2.0	5.4	2.1	5.8	10.5	1.8	6.0	0.7	1.3	2.0	1.3	5.4	7.3	0.6	0.9	1.4	0.9	0.6	3.5
24 高島 忠六別水門	6.1	2.8	4.4	1.5	7.4	3.2	1.5	5.8	1.8	5.4	5.0	0.9	4.7	0.9	0.8	1.9	1.4	5.4	8.7	2.8	2.0	2.1	1.8	0.9	3.3
25 金納橋	6.5	3.2	5.0	2.1	6.4	5.2	1.7	5.9	1.8	4.6	5.5	1.1	3.5	1.1	0.9	2.0	5.2	8.4	8.6	2.2	2.6	1.7	1.7	1.1	3.7
26 東蒲池 榎木いび	7.2	4.4	4.7	1.5	4.7	4.0	1.3	5.3	1.7	4.7	5.3	1.3	4.6	1.4	9.1	5.0	3.5	6.8	9.9	2.4	2.8	1.7	1.2	1.1	4.0
27 西浜武ファインテック東側	7.6	5.2	3.0	1.9	5.0	6.1	1.8	6.1	1.2	5.0	6.8	1.2	4.0	0.7	0.9	8.7	4.3	5.0	5.5	1.2	1.8	3.9	1.5	1.3	3.7
28 昭代第二小学校西側	8.3	5.0	4.7	3.8	5.2	4.1	1.9	9.1	2.4	6.0	7.0	1.8	3.7	1.1	4.3	5.3	3.8	7.4	9.1	1.2	1.8	4.7	1.2	1.4	4.3
29 吉原南バス停東側	9.0	5.8	4.8	10.7	6.1	6.7	3.2	9.7	2.7	6.6	8.5	3.8	4.5	1.1	1.7	5.2	6.4	8.5	11.5	1.2	1.7	11.3	1.7	1.5	5.6
30 柳川みのり幼稚園東側	10.5	6.5	4.7	4.8	5.1	5.4	3.1	9.1	2.4	6.4	7.7	2.1	5.0	1.1	3.5	8.6	7.4	6.7	4.7	1.2	1.8	5.8	1.4	1.2	4.8
31 間九郎丸橋	12.0	9.7	7.4	9.4	6.3	11.7	3.4	11.3	3.5	7.8	9.2	10.6	5.0	3.2	10.0	5.1	8.9	9.1	9.2	1.7	3.7	13.3	2.1	1.9	7.3
32 昭代6号線 池町制水門	9.2	7.9	5.7	7.2	6.0	11.0	2.8	8.3	1.9	6.0	8.9	5.9	3.7	2.5	4.8	5.8	7.0	8.7	6.4	1.8	1.8	3.7	1.4	1.7	5.4
平均	7.8	5.0	6.4	4.9	4.6	5.4	2.1	5.0	2.6	4.0	5.8	2.7	4.6	3.1	3.7	4.4	4.2	8.1	9.2	2.2	2.5	4.5	1.4	2.2	4.4