


# 令和2年4月～令和3年3月 平均BOD値 (mg/リットル)



**【参考】**  
 環境基準(河川)  
 A類型: 2mg/リットル

令和2年度 BOD(mg/l)測定結果

採水日	4/1	4/1 6	5/1	5/18	6/1	6/16	7/1	7/16	8/3	8/17	9/1	9/16	10/1	10/16	11/2	11/16	12/1	12/16	1/4	1/18	2/1	2/16	3/1	3/16	平均値
1 徳益・垂見 下田橋南側	15.0	0.6	1.1	1.2	1.7	30.7	12.3	13.9	2.6	0.6	1.1	1.5	1.5	3.0	3.2	1.5	1.1	2.1	2.1	2.0	1.4	2.1	9.1	1.8	4.7
2 南徳益流川橋西側	12.0	24.3	11.7	24.8	11.2	5.8	22.0	12.4	4.0	1.1	3.1	7.0	19.4	14.6	25.5	24.3	12.9	0.8	2.4	19.1	24.6	12.8	12.6	13.1	13.4
3 豊原小学校西側	2.6	0.8	3.0	2.0	1.9	26.4	8.5	14.2	3.1	1.8	3.2	2.5	2.2	9.2	7.1	4.7	4.3	2.6	3.4	4.4	3.3	3.7	6.1	3.2	5.2
4 鷹尾交差点東側	2.0	0.8	2.1	3.3	2.2	24.8	12.2	13.8	3.4	1.8	7.1	2.4	7.9	21.5	15.2	10.7	5.7	1.2	2.0	3.8	2.5	5.4	12.8	3.4	7.0
5 皿垣小学校西側	2.2	0.8	3.0	0.8	2.4	6.0	16.2	15.5	3.4	0.7	3.9	1.9	3.4	6.3	5.8	3.4	4.6	2.2	5.3	3.2	2.2	7.4	13.1	3.5	4.9
6 二十五丁水門	1.7	1.1	2.1	2.6	4.0	6.8	14.0	24.8	6.3	1.1	1.8	2.1	8.6	10.6	12.4	9.0	3.9	3.3	8.5	5.5	5.1	2.2	8.5	4.4	6.3
7 中島二重橋平河建材北側	1.5	3.3	10.5	1.8	3.0	3.0	0.8	1.9	1.7	0.7	1.9	1.3	1.4	4.8	4.5	0.8	13.1	10.3	15.5	5.0	4.1	5.1	19.8	21.7	5.7
8 中島東上町公民館西側	3.2	1.2	13.0	3.8	3.9	8.6	6.7	12.0	2.2	0.8	4.1	2.5	13.1	15.7	11.3	10.5	5.8	1.8	5.0	4.8	3.3	6.5	12.4	5.8	6.6
9 六合配水場東側	1.8	0.7	0.7	0.7	2.6	15.2	7.4	8.1	1.1	0.7	0.8	0.7	1.8	2.7	1.7	0.7	2.7	1.1	0.8	1.7	2.2	4.1	9.0	1.7	2.9
10 立花いこいの森駐車場南側	0.6	0.6	0.6	0.6	1.1	1.4	1.2	4.6	0.7	0.6	0.8	0.6	0.6	1.9	0.8	0.6	1.2	0.6	1.4	0.6	0.6	0.8	6.5	0.7	1.2
11 百町 ニツ川樋管	5.9	0.7	0.6	0.7	1.3	1.5	0.9	4.4	0.6	0.6	0.6	0.6	0.9	2.0	0.6	2.0	1.4	0.6	2.8	1.1	0.6	0.6	6.0	0.6	1.6
12 吉開納骨堂西側	3.8	2.6	10.5	1.1	3.3	3.5	5.2	12.3	1.9	2.4	3.9	1.2	2.0	5.8	4.3	5.1	6.5	2.6	5.4	4.1	5.8	3.0	11.0	3.5	4.6
13 起田天満神社北側	1.8	1.8	16.1	1.2	4.5	5.0	4.6	10.0	8.0	2.2	4.3	1.9	4.7	10.2	8.1	7.0	12.3	10.6	10.8	9.2	12.8	6.1	13.6	6.4	7.2
14 磯鳥ポンプ場北側	1.7	2.6	0.8	1.1	2.2	2.6	4.0	8.6	0.6	0.6	0.6	0.6	2.0	3.4	1.5	1.5	1.7	2.0	3.7	2.6	2.5	1.4	9.6	2.5	2.5
15 散田 ニツ川有明海岸道路東側	0.6	0.9	0.6	0.6	2.4	1.4	1.8	4.4	0.6	0.6	0.8	0.6	2.1	2.2	0.6	2.0	1.8	0.6	2.5	0.7	1.5	0.6	6.5	0.6	1.5
16 柳川駅南側	2.8	1.5	7.6	1.9	3.8	7.7	8.3	7.2	1.9	0.6	1.9	0.7	5.3	5.0	2.0	3.3	2.6	0.6	3.9	1.9	2.4	2.7	9.0	3.0	3.7
17 枝光小坪樋管	1.8	3.4	11.9	3.2	3.7	7.4	7.8	9.4	0.7	0.6	1.9	0.8	5.8	10.6	4.5	4.6	9.2	7.4	7.8	4.3	3.7	4.5	11.5	6.4	5.5
18 三柱神社西側 宮地嶽ポンプ場	0.6	1.2	1.3	0.7	2.4	2.2	2.5	5.8	0.6	0.6	2.2	0.6	3.4	4.1	2.2	5.3	3.8	1.8	3.3	2.1	1.9	0.7	6.4	1.3	2.4
19 柳川市葬祭取扱所北側	0.7	1.8	1.7	0.6	3.0	2.7	3.5	3.7	0.6	0.6	1.8	0.8	6.3	2.8	1.3	3.5	3.1	1.9	2.4	0.6	0.6	0.9	7.1	0.7	2.2
20 坂本町 弥兵衛門橋	0.6	1.1	0.6	0.7	2.2	2.8	4.3	7.4	0.6	0.6	1.5	0.6	5.1	2.6	1.2	3.2	2.2	0.6	3.0	2.0	0.6	1.4	6.3	0.8	2.2
21 松濤園南側 八幡樋管	0.9	1.2	0.8	0.9	6.7	3.9	3.3	5.5	0.6	0.6	2.4	0.7	3.8	3.9	1.8	4.1	2.4	0.6	3.1	1.5	1.8	2.2	6.6	1.1	2.5
22 東宮永小学校東側	5.8	1.4	0.6	1.1	2.2	3.5	5.1	7.3	0.6	0.6	1.4	0.6	3.8	3.5	0.7	5.1	1.7	0.6	5.2	1.8	0.7	2.5	5.7	0.7	2.6
23 中六十丁公民館西側	12.6	1.7	1.8	1.5	4.5	12.6	11.1	19.4	1.9	1.4	1.4	3.9	5.3	6.3	3.1	9.0	3.8	1.3	4.3	4.6	12.2	5.9	10.9	4.4	6.0
24 高島 忠六別水門	4.1	2.5	1.2	1.5	3.1	14.6	13.9	14.5	0.8	0.8	4.5	1.2	4.7	6.0	2.4	4.1	3.9	1.7	5.5	1.8	1.5	4.3	5.9	3.2	4.5
25 金納橋	4.0	2.6	1.2	1.4	4.3	14.8	13.0	15.0	0.8	1.1	4.1	1.2	5.9	5.7	2.4	5.7	5.1	1.9	5.5	3.8	1.9	5.0	6.4	3.2	4.8
26 東蒲池 榎木いび	2.0	2.7	1.7	1.5	3.5	12.0	12.8	15.1	1.1	1.1	5.2	1.2	5.0	5.9	3.5	6.4	5.5	5.3	5.4	3.7	4.7	4.4	4.6	2.5	4.9
27 西浜武ファインテック東側	15.3	4.1	4.1	23.1	5.7	10.2	11.2	13.6	0.7	0.8	3.1	0.8	4.3	4.4	2.7	8.3	5.9	6.4	5.2	9.9	2.0	4.6	4.6	5.0	6.5
28 昭代第二小学校西側	22.4	4.0	4.0	4.0	4.3	11.6	11.3	11.6	0.9	0.8	2.8	1.2	5.0	5.8	5.4	11.6	5.4	7.8	6.7	5.5	1.5	6.1	5.7	5.2	6.3
29 吉原南バス停東側	23.4	3.2	5.1	10.3	4.1	14.9	14.8	12.4	1.1	1.1	2.6	1.2	6.1	8.3	8.7	7.8	7.6	5.8	6.1	5.7	3.7	12.0	5.8	8.7	7.5
30 柳川みのり幼稚園東側	14.0	3.1	2.5	5.5	4.5	12.8	12.4	15.6	2.6	1.2	2.7	1.9	8.0	7.9	5.5	6.3	4.7	4.4	7.1	5.3	2.8	7.3	6.3	6.8	6.3
31 間九郎丸橋	21.0	4.8	5.3	10.6	7.3	9.4	8.3	11.7	2.5	3.2	3.7	1.8	12.5	19.1	13.8	5.9	6.7	7.7	10.0	6.5	7.7	11.0	9.8	8.6	8.7
32 昭代6号線 池町制水門	10.6	4.3	2.7	4.3	4.8	11.9	11.7	11.9	1.1	1.5	3.1	1.7	7.6	7.3	6.6	7.3	8.9	4.6	8.9	5.3	6.0	8.7	8.1	9.4	6.6
平均	6.2	2.7	4.1	3.7	3.7	9.3	8.5	10.9	1.9	1.0	2.6	1.5	5.3	7.0	5.3	5.8	5.0	3.2	5.2	4.2	4.0	4.6	8.7	4.5	5.0